

HAZARDOUS FIRE AREA Brush Clearance

REQUIREMENTS

- A. All flammable vegetation must be cleared a MINIMUM of 30 feet around structures. Ornamental shrubbery and trees cleared of dead leaves and branches
- B. Roofs, eaves, and rain gutters must be cleared of pine needles, leaves, or other dead or dying wood.
- C. Tree limbs shall be cut within 10 feet of chimneys and / or stovepipes. Dead limbs hanging over house or garage must be trimmed.
- D. Chimney outlets or flue shall be covered with a spark arresting 1/2" mesh screen
- E. Address shall be clearly visible for easy identification in an emergency

RECOMMENDATIONS

- F. Trees 18 feet or taller should be limbed 6 feet up from the ground
- G. Woodpiles should be stacked a minimum of 30 feet from building, fences, and other combustible materials
- H. All vegetation and other flammable materials should be cleared from beneath decks. Elevated decks should be enclosed with fire resistive materials.